



Bridge	Landing or Log Deck	Value at Risk	Road as Completed Line
Camp	Mobile Weather Unit	Other	Access or Improved Road
Closure	Repair Point	MANDATORY EXCLUSION AREA	Aerial Retardant Drop
Culvert	Repeater	MANDATORY EXCLUSION AREA	Repair Line
Dip Site	Resource Location	MANDATORY EXCLUSION AREA	Road Repair
Drop Point	Retardant in Avoidance Area	MANDATORY EXCLUSION AREA	Penstocks
Dozer Push	Road Repair	Mine	Event Polygon
Fire Station	Safety Zone	WoodBridges	MANDATORY EXCLUSION AREA
Gate	Spot Fire	Structure	cnty19_1_basic
Hazard	Staging Area	Contained Line	Roads Open to All Vehicles, Yearlong
Hazard Tree	Stream Crossing	Completed Dozer Line	Roads Open to Highway Legal Vehicles Only, Yearlong
Helispot	Water Source	Completed Hand Line	
Internet Access	Restricted Water Source		
Landmark	Water Development or Draft Site		

REPAIR/OPERATIONS

North Complex
CA-PNF-001308
10/18/2020
North Branch- Page 1

Repair Status

- Completed - Inspection
- Completed - Ready for Inspection
- In Progress
- In Use - Fire Management
- No Repair Needed
- Other - See Comments
- Repair Needed
- Warning

0 1 Miles
1:26,000
Map Updated: 10/17/2020 23:30