REPAIR / OPS

10/23/20 - 10/25/2020

REPAIR/OPERATIONS

North Complex

CA-PNF-001308

10/23/2020 - 10/25/2020

South Branch- Page 1

Quincy
East Quincy
Spring Garden
Cromberg
Plumas Eureka
Johnsville
DIV Z
DIV BB
Sierra County
Plumas County
PLUMAS NATIONAL FOREST
GRAEAGLE RIDGE
MIDDLE FORK FEATHER WILD AND SCENIC RIVER

MajorCities
Aerial Hazard
Bridge
Culvert
Dip Site
Drop Point
Dozer Push
Fence - Cut/Damaged
Fire Station
Gate
Hazard
Hazard Tree
Helispot
Incident Command Post
Internet Access
Landing or Log Deck
Lookout
Mobile Weather Unit
Repair Point
Repeater
Resource Location
Retardant In Avoidance Area
Safety Zone
Staging Area
Stream Crossing
Structure Wrap
Water Source
Water Development or Draft Site
Value at Risk
Other
Division Break
SPI Gate
MANDATORY EXCLUSION AREA
MANDATORY EXCLUSION AREA
MANDATORY EXCLUSION AREA
Mine
Structure
SPI Fuelbreak
Contained Line
Completed Dozer Line
Completed Hand Line
Road as Completed Line
Access or Improved Road
Completed Plow Line
Aerial Retardant Drop
Repair Line
Road Repair
Event_Polygon
MANDATORY EXCLUSION AREA
cnty19_1_basic
Roads Open to All Vehicles, Yearlong
Roads Open to Highway Legal Vehicles Only, Yearlong

Repair Status
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- In Use - Fire Management
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Land Owner
- BLM
- Other Private
- Sierra Pacific Industries
- Soper-Wheeler
- State Land
- USDA Forest Service
- National Park
- Local Government
- US FWS
- Other Federal
- Tribal Land
- Label Point



0 1 2 Miles

1:28,000

Map Updated:10/23/2020 10:25