
Suppression Repair - North Complex
CA-PNF-001308
November 2, 2020
Completed - Inspected
Repair Needed
Completed - Ready for Inspection
Other - See Comments
In Progress
Unknown
0
1
2
3
4
Miles
N
DIV OO
DIV Z
DIV BB
DIV DD
DIV GG
DIV C
SOUTH BRANCH
Plumas County
Butte County
Yuba County
Dome Dip
Foresbay Dip
Open Mine Shaft
RAWS-16
H-3
Quarry Dip
Meadow Valley Fire Station
Scheinder Dip
North Complex ICP
East Quincy Dip
RiverNetwork Dip
Gravel Dip
Poplar Dip
Eureka Ridge #58
H-10
Fowler Dip
Four Open Mine Shafts
Grass Dip
Peninsula Spike
Bald Check
Back-in Draft Only
RAWS-2
Heavy Equipment
Forbestown Dip
Chimney
Dry #1
Bald Check
Enterprise Flat Dip
Bridge #1
Spring Dip
Woodleaf
EAST QUINCY
QUINCY
MEADOW VALLEY
TORRIE
TOBIN
BUCKS LAKE
GREENHORN
SPRING GARDEN
CROMBERG
JOHNSVILLE
LITTLE GRASS VALLEY
LA PORTE
DOWNIEVILLE
GOODYEARS BAR
BERRY CREEK
CLIPPER MILLS
FORBES
CHALLENGE-BROWNSVILLE
GRAEAGLE