


Drop Point	MANDATORY EXCLUSION AREA	Event Polygon
Door Push	Contained Line	Line/DEMarcation
Repair Point	Completed Door Line	Valley Creek Special Interest Area
Stream Crossing	Completed Road Line	Roads Open to All Vehicles, Yearlong
Water Source	Road as Completed Line	Roads Open to Highway Legal Vehicles Only, Yearlong
Other	Access or Improved Road	Road Repair
SFI Gate		

Repair Status	
Green circle	Completed - Inspected
Yellow circle	Completed - Ready for Inspection
Yellow circle with border	In Progress
Grey circle	In Use - Fire Management
Grey circle	No Repair Needed
Red circle	Other - See Comments
Purple circle	Repair Needed
Purple circle	Unknown

Land Owner	
Light blue	BLM
Light green	Other Private
Light purple	Sierra Pacific Industries
Light blue	Soper-Wheeler
Light green	State Land
Light green	USDA Forest Service
Light green	National Park
Light blue	Local Government
Light blue	US FWS
Light blue	Other Federal
Light blue	Tribal Land

REPAIR/OPERATIONS

North Complex
CA-PNF-001308
11/3/2020
Group 1 Mooreville Ridge



Map Updated: 11/3/2020 4:34 PM