



Prepared by CRIM12 9/24/2021 19:39

- Aerial Hazard
- Check Point
- Dip Site
- Helibase
- Division Break
- Branch Break
- Camp
- Staging Area
- Clean Up Area
- Mobile Weather Unit
- Gate
- Structure Wrap
- Stream Crossing
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Access or Improved Road
- Road Repair
- Retardant Drop
- Contained Line
- Completed - Inspected
- Repair Needed
- Other - See Comments
- Unknown
- Completed - Inspected
- Repair Needed
- No Repair Needed
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

# SUPPRESSION REPAIR

## Caldor

### CA-ENF-24030

09/25/21



0 0.75 1.5 3 Miles  
140,000 NAD83 UTM 11N

Caldor  
CA-ENF-24030  
**REPAIR**  
Branch I  
09/25/21