


Prepared by: CAJIM113 10/4/2021 01:00

<ul style="list-style-type: none"> <li>Aerial Hazard</li> <li>Check Point</li> <li>Dip Site</li> <li>Mobile Retardant Base</li> <li>Helibase</li> <li>Sling Site</li> <li>Unimproved Landing Area</li> <li>Crane Break</li> <li>Branch Break</li> <li>Crane Break</li> <li>Drop Point</li> <li>Camp</li> <li>Staging Area</li> <li>Water at Risk</li> <li>Other</li> <li>Gate</li> <li>Bridge</li> <li>Water Development or Draft Site</li> <li>Structure Wreck</li> <li>Stream Crossing</li> <li>Road Repair</li> </ul>	<ul style="list-style-type: none"> <li>Retardant in Avoidance Area</li> <li>Resource Location</li> <li>Repair Point</li> <li>Landing or Log Deck</li> <li>Hazard Tree</li> <li>Fence - Cut/Damaged</li> <li>Disser Path</li> <li>Close Up Area</li> <li>Mobile Weather Unit</li> <li>Internet Access</li> <li>Repeater</li> <li>Hazard</li> <li>Water Source</li> <li>Other</li> <li>Completed Disser Line</li> <li>Completed Fuel Break</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Planned Road Line</li> <li>Repair Needed</li> </ul>	<ul style="list-style-type: none"> <li>Access or Improved Road</li> <li>Other - See Comments</li> <li>Unknown</li> <li>California Wildland Fire Direct Protection Areas - 2021</li> <li>DPA_GROUP</li> <li>LOCAL</li> <li>STATE</li> <li>COMPLETE</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> </ul>	<ul style="list-style-type: none"> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>California Wildland Fire Direct Protection Areas - 2021</li> <li>DPA_GROUP</li> <li>LOCAL</li> <li>STATE</li> <li>COMPLETE</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> </ul>
--	--	---	--

# SUPPRESSION REPAIR REPORTING AREAS

## Caldor

CA-ENF-24030  
October 4, 2021



REPAIR  
Report  
Caldor  
CA-ENF-24030