



Branch I

Div G

Div D

Div A

Div W

Div T

# SUPPRESSION REPAIR

**Caldor**  
 CA-ENF-24030  
 October 7, 2021

**REPAIR**  
 Branch I  
 Caldor  
 CA-ENF-24030



Event Point	Road Repair	Completed Fuel Break	Repair Status Line
Aerial Hazard	Retardant in Avoidance Area	Completed Hand Line	Completed - Inspected
Check Point	Repair Point	Completed Mixed Construction Line	Completed - Ready for Inspection
Dip Site	Landing or Log Deck	Completed Road as Line	In Progress
Division Break	Hazard Tree	Access or Improved Road	Repair Needed
Drop Point	Fence - Cut/Damaged	Retardant Drop	No Repair Needed
Staging Area	Power Path	Contained Line	Other - See Comments
Camp	Clean Up Area	California Wildland Fire Direct Protection Areas - 2021	Unknown
Mobile Weather Unit	Internet Access	FEDERAL	
Other	Repeater	STATE	
Gate	Water Source	LOCAL	
Structure Wrap	Event Line	Completed - Inspected	
Stream Crossing	Completed Dozer Line	Repair Needed	
		No Repair Needed	
		Other - See Comments	
		Unknown	

