

Branch I

Div G

Div D

Div A  
Caldor Check 3500

Div T

Div W


# SUPPRESSION REPAIR

Caldor  
CA-ENF-24030

October 10, 2021



Event Point	Road Repair	Completed Hand Line	Repair Status Line
Aerial Hazard	Retardant in Avoidance Area	Completed Mixed Construction Line	Completed - Inspected
Check Point	Repair Point	Completed Road as Line	Completed - Ready for Inspection
Dip Site	Landing or Log Deck	Access or Improved Road	In Progress
Hillbase	Hazard Tree	Road Repair	Repair Needed
Division Break	Fence - Cut/Damaged	Retardant Drop	No Repair Needed
Branch Break	Dozer Push	Contained Line	Other - See Comments
Drop Point	Clean Up Area	Trail	Unknown
Camp	Mobile Weather Unit	California Wildland Fire Direct Protection Areas - 2021	FEDERAL
Staging Area	Internet Access	Repair Status Point	STATE
Value at Risk	Responder	Completed - Inspected	LOCAL
Water Source	Water Source	Repair Needed	No Repair Needed
Gate	Event Line	Other - See Comments	Secondary Fuel Breaks
Structure Wrap	Completed Dozer Line	Unknown	Haz/Tree Priority Roads
Stream Crossing	Completed Fuel Break	Unknown	Primary Fuel Breaks



REPAIR  
Branch I  
Caldor  
October 10, 2021  
CA-ENF-24030

0 0.75 1.5 3 Miles  
1:40,000 NAD83 UTM 11N