

N
W E
S

Prepared by: GB Team 7 10/12/2021 20:39

Event Point
- Aerial Hazard
- Check Point
- Dip Site
- Helibase
- Division Break
- Drop Point
- Staging Area
- Value at Risk
- Other
- Gate
- Structure Wrap
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Fence - Cut/Damaged
- Dozer Push
- Clean Up Area
- Mobile Weather Unit
- Internet Access
- Repeater
- Water Source

Event Line
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Access or Improved Road
- Road Repair
- Retardant Drop
- Contained Line

Trail
- Trail

Repair Status Point
- Completed - Inspected
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

Repair Status Line
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

California Wildland Fire Direct Protection Areas - 2021
- FEDERAL
- STATE
- LOCAL
- Secondary Fuel Breaks
- HazTree PriorityRoads
- Primary Fuel Breaks

SUPPRESSION REPAIR

Caldor

CA-ENF-24030

October 13, 2021

0 0.75 1.5 3 Miles

1:40,000 NAD83 UTM 11N

REPAIR WEST

Caldor

CA-ENF-24030

October 13, 2021