


- | | | | | |
|---|--|---|---|---|
| <ul style="list-style-type: none"> Other Property Pump Water Tank Helispot Sling Site Division Break Drop Point Staging Area Lookout Road Repair Repair Point Fence - Cut/Damaged Dozer Push Clean Up Area Mobile Weather Unit Repeater Hazard Water Source | <ul style="list-style-type: none"> Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Hand Line Repair Line Road Repair Route Contained Line Wildfire Daily Fire Perimeter Forest Service Land State Public Lands Other State Lands Private; Local Government; Undesignated Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads | <p>Repair Status Accountable Property</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown | <p>Repair Status Line</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown | <p>Repair Status Point</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection |
|---|--|---|---|---|

- | |
|---|
| <ul style="list-style-type: none"> In Progress Repair Needed No Repair Needed Other - See Comments Unknown |
|---|

Meyer Repair Area - Echo

Caldor
CA-ENF-24030
October 15, 2021



0 0.35 0.7 1.4 Miles
1:18,000
NAD83 UTM 11N
Prepared by: GB Team 7 10/14/2021 21:40

