



- | | | |
|------------------------|----------------------------------|----------------------|
| Drop Point | In Use - Fire Management | Other - See Comments |
| Completed Dozer Line | Completed - Ready for Inspection | Unknown |
| Forest Service Land | In Progress | |
| HazTree Priority Roads | Repair Needed | |
| Repair Status | No Repair Needed | |
| Completed - Inspected | | |

Meyer Repair Area - DP72 Road Work
 Caldor
 CA-ENF-24030
 October 19, 2021

