DIV OQR Suppression Repair

10/06/2021

Feature Category	Repair Status	Feature Count
Aerial Hazard	No Repair Needed	1
Branch Break	Unknown	2
Bridge	No Repair Needed	33
Bridge	Other - See Comments	1
Bridge	Repair Needed	2
Bridge	Unknown	16
Camp	Unknown	2
Check Point	Unknown	5
Clean Up Area	Repair Needed	10
Closure	No Repair Needed	1
Culvert	No Repair Needed	1
Culvert	Repair Needed	6
Culvert	Unknown	1
Division Break	Unknown	8
Dozer Push	Completed - Inspected	5
Dozer Push	In Progress	1
Dozer Push	No Repair Needed	5
Dozer Push	Other - See Comments	2
Dozer Push	Repair Needed	40
Dozer Push	Unknown	3
Drop Point	Completed - Inspected	1
Drop Point	No Repair Needed	15
Drop Point	Repair Needed	3
Drop Point	Unknown	20
Gate	No Repair Needed	88
Gate	Repair Needed	1
Gate	Unknown	351
Hazard	No Repair Needed	3
Hazard	Other - See Comments	1
Hazard	Repair Needed	4
Hazard	Unknown	7
Hazard Tree	No Repair Needed	1
Hazard Tree	Repair Needed	3
Helibase	Unknown	1
Helispot	No Repair Needed	2
Helispot	Unknown	16
Hot Spot - Spot Fire	No Repair Needed	1
Hot Spot - Spot Fire	Unknown	9
Internet Access	No Repair Needed	5
Internet Access	Unknown	4
Landing or Log Deck	Repair Needed	1
Landmark	No Repair Needed	1
Landmark	Unknown	2
Lookout	No Repair Needed	2
Lookout	Unknown	4
Mobile Weather Unit	No Repair Needed	2
Mobile Weather Unit	Unknown	6
Other	Completed - Inspected	3
Other	No Repair Needed	17
Other	Other - See Comments	4
Other	Repair Needed	8
Other	Unknown	18
Repair Point	Completed - Inspected	1
Repair Point	In Progress	1
Repair Point	No Repair Needed	2
Repair Point	Other - See Comments	2
Repair Point	Repair Needed	55
Repair Point	Unknown	6
Repeater	No Repair Needed	2
Repeater	Unknown	5
Resource Location	No Repair Needed	1
Resource Location	Repair Needed	4
Resource Location	Unknown	2
Restricted Water Source	No Repair Needed	3
Restricted Water Source	Unknown	1
Road Repair	Completed - Inspected	4
Road Repair	In Progress	2
Road Repair	No Repair Needed	1
Road Repair	Repair Needed	26
Road Repair	Unknown	1
Sling Site	No Repair Needed	1
Sling Site	Unknown	6
Staging Area	Completed - Inspected	1
Staging Area	No Repair Needed	1
Staging Area	Repair Needed	9
Staging Area	Unknown	4
Stream Crossing	No Repair Needed	3
Stream Crossing	Other - See Comments	1
Stream Crossing	Repair Needed	3
Stream Crossing	Unknown	9
Structure Wrap	Repair Needed	1
Structure Wrap	Unknown	3
Value at Risk	No Repair Needed	25
Value at Risk	Repair Needed	8
Value at Risk	Unknown	8
Water Development or Draft Site	Completed - Inspected	2
Water Development or Draft Site	In Use - Fire Management	1
Water Development or Draft Site	No Repair Needed	5
Water Development or Draft Site	Repair Needed	3
Water Development or Draft Site	Unknown	5
Water Source	Completed - Inspected	1
Water Source	No Repair Needed	42
Water Source	Unknown	48

Feature Category	Repair Status	Feature Count	Length (Ft)	Length (Mi)
Access or Improved Road	Completed - Inspected	1	34,251	6.5
Access or Improved Road	In Progress	2	46,425	8.8
Access or Improved Road	In Use - Fire Management	1	3,198	0.7
Access or Improved Road	No Repair Needed	274	627,981	118.9
Access or Improved Road	Other - See Comments	1	2,664	0.5
Access or Improved Road	Repair Needed	20	137,856	26.1
Access or Improved Road	Unknown	66	62,319	11.8
Completed Burnout	No Repair Needed	1	8,473	1.6
Completed Dozer Line	Completed - Inspected	55	1,655,669	313.4
Completed Dozer Line	Completed - Ready for Inspection	3	13,892	2.6
Completed Dozer Line	In Progress	30	1,033,171	195.5
Completed Dozer Line	In Use - Fire Management	5	8,055	1.5
Completed Dozer Line	No Repair Needed	34	31,388	5.9
Completed Dozer Line	Other - See Comments	2	2,236	0.2
Completed Dozer Line	Repair Needed	205	346,294	65.6
Completed Dozer Line	Unknown	48	73,635	13.9
Completed Fuel Break	No Repair Needed	6	30,596	5.9
Completed Fuel Break	Repair Needed	1	7,971	1.5
Completed Fuel Break	Unknown	1	5,474	1
Completed Hand Line	Completed - Inspected	2	4,824	0.9
Completed Hand Line	In Progress	4	36,121	6.8
Completed Hand Line	In Use - Fire Management	3	9,231	1.7
Completed Hand Line	No Repair Needed	26	38,330	7.3
Completed Hand Line	Repair Needed	102	149,656	28.3
Completed Hand Line	Unknown	53	75,505	14.3
Completed Mixed Construction Line	In Progress	3	13,835	2.8
Completed Mixed Construction Line	In Use - Fire Management	1	957	0.2
Completed Mixed Construction Line	No Repair Needed	4	14,706	2.8
Completed Mixed Construction Line	Other - See Comments	1	1,175	0.2
Completed Mixed Construction Line	Repair Needed	9	51,233	9.9
Completed Mixed Construction Line	Unknown	3	10,306	2
Completed Road as Line	Completed - Inspected	8	71,919	13.6
Completed Road as Line	In Progress	7	17,593	3.3
Completed Road as Line	In Use - Fire Management	1	13,942	2.7
Completed Road as Line	No Repair Needed	38	202,140	38.3
Completed Road as Line	Other - See Comments	2	22,308	4.4
Completed Road as Line	Repair Needed	56	233,792	44.3
Completed Road as Line	Unknown	15	67,405	12.5
Contained Line	No Repair Needed	4	1,567,053	296.8
Contained Line	Repair Needed	1	16,798	3.2
Contained Line	Unknown	116	1,105,073	201
Fire Edge	Unknown	61	925,166	175.2
Planned Dozer Line	No Repair Needed	2	16,679	3.3
Planned Dozer Line	Unknown	16	97,445	18.5
Planned Hand Line	No Repair Needed	1	5,970	0.9
Planned Hand Line	Other - See Comments	1	6,109	1.2
Planned Hand Line	Unknown	11	31,269	5.9
Planned Mixed Construction Line	No Repair Needed	5	94,461	17.9
Planned Mixed Construction Line	Unknown	4	40,619	7.7
Planned Road as Line	No Repair Needed	7	88,311	16.7
Planned Road as Line	Unknown	12	148,193	28.1

Completed - Inspected
In Use - Fire Management
Completed - Ready for Inspection
In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown
Fire Edge

Contained Line
Completed Dozer Line
Completed Fuel Break
H - Completed Hand Line
M - Completed Mixed Construction Line
R - Completed Road as Line
Planned Dozer Line
H - Planned Hand Line

M - Planned Mixed Construction Line
R - Planned Road as Line
Access or Improved Road
Retardant Drop
Aerial Hazard
Check Point
Helispot
Helibase

Sling Site
Division Break
Drop Point
Camp
Staging Area
Lookout
Hot Spot - Spot Fire
Value at Risk

Other
Landmark
Gate
Bridge
Water Development or Draft Site
Structure Wrap
Stream Crossing
Road Repair

Resource Location
Repair Point
Hazard Tree
Dozer Push
Culvert
Clean Up Area
Mobile Weather Unit
Internet Access
Repeater

Hazard
Water Source
Restricted Water Source
Other Property
Pump
Water Tank
Completed - Inspected
In Use - Fire Management

In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown
Section Protracted
Section
Private Timberland

Suppression Repair

River Complex
CA-KNF-006385
10/06/2021 07:00

0 1 2 3 Miles
1:40,000