IN PROGRESS Suppression Repair

10/13/2021

Feature Category	Repair Status	Feature Count
Aerial Hazard	No Repair Needed	1
Bridge	No Repair Needed	38
Bridge	Other - See Comments	2
Bridge	Repair Needed	1
Bridge	Unknown	9
Camp	Unknown	2
Check Point	No Repair Needed	1
Check Point	Unknown	1
Clean Up Area	Completed - Inspected	5
Clean Up Area	Other - See Comments	1
Clean Up Area	Repair Needed	4
Culverts	No Repair Needed	1
Culvert	Completed - Inspected	1
Culvert	No Repair Needed	1
Culvert	Other - See Comments	2
Culvert	Repair Needed	4
Culvert	Unknown	1
Division Break	Unknown	10
Dozer Push	Completed - Inspected	13
Dozer Push	In Progress	2
Dozer Push	No Repair Needed	5
Dozer Push	Other - See Comments	2
Dozer Push	Repair Needed	38
Dozer Push	Unknown	1
Drop Points	Completed - Inspected	3
Drop Point	No Repair Needed	24
Drop Point	Repair Needed	1
Drop Point	Unknown	25
Gate	No Repair Needed	179
Gate	Other - See Comments	1
Gate	Repair Needed	1
Gate	Unknown	164
Hazard	No Repair Needed	7
Hazard	Other - See Comments	2
Hazard	Repair Needed	4
Hazard	Unknown	3
Hazard Tree	Completed - Inspected	2
Hazard Tree	No Repair Needed	1
Hazard Tree	Repair Needed	1
Helibase	Unknown	1
Helispot	In Progress	1
Helispot	No Repair Needed	12
Helispot	Unknown	1
Hot Spot - Spot Fire	No Repair Needed	1
Hot Spot - Spot Fire	Unknown	9
Incident Command Post	Unknown	1
Internet Access	No Repair Needed	2
Internet Access	Unknown	2
Landing or Log Deck	In Progress	1
Landmark	No Repair Needed	2
Lookout	No Repair Needed	3
Lookout	Unknown	2
Mobile Weather Unit	No Repair Needed	2
Mobile Weather Unit	Unknown	1
Other	Completed - Inspected	3
Other	No Repair Needed	23
Other	Other - See Comments	4
Other	Repair Needed	10
Other	Unknown	13
Repair Point	Completed - Inspected	11
Repair Point	In Progress	3
Repair Point	No Repair Needed	4
Repair Point	Other - See Comments	2
Repair Point	Repair Needed	36
Repair Point	Unknown	3
Repeater	No Repair Needed	3
Repeater	Unknown	4
Resource Location	No Repair Needed	2
Resource Location	Other - See Comments	1
Resource Location	Repair Needed	4
Resource Location	Unknown	1
Restricted Water Source	No Repair Needed	3
Restricted Water Source	Unknown	1
Road Repair	Completed - Inspected	9
Road Repair	In Progress	2
Road Repair	No Repair Needed	4
Road Repair	Other - See Comments	1
Road Repair	Repair Needed	18
Road Repair	Unknown	3
Sling Site	No Repair Needed	4
Sling Site	Unknown	3
Staging Area	Completed - Inspected	3
Staging Area	In Progress	3
Staging Area	No Repair Needed	3
Staging Area	Repair Needed	7
Staging Area	Unknown	2
Stream Crossing	No Repair Needed	4
Stream Crossing	Other - See Comments	1
Stream Crossing	Repair Needed	4
Stream Crossing	Unknown	9
Structure Wrap	Completed - Inspected	3
Structure Wrap	Repair Needed	2
Structure Wrap	Unknown	2
Value at Risk	Completed - Inspected	3
Value at Risk	No Repair Needed	27
Value at Risk	Other - See Comments	1
Value at Risk	Repair Needed	4
Value at Risk	Unknown	5
Water Development or Draft Site	Completed - Inspected	2
Water Development or Draft Site	In Use - Fire Management	1
Water Development or Draft Site	No Repair Needed	6
Water Development or Draft Site	Repair Needed	4
Water Development or Draft Site	Unknown	1
Water Source	Completed - Inspected	1
Water Source	No Repair Needed	45

Feature Category	Repair Status	Feature Count	Length mi
Access or Improved Road	Completed - Inspected	8	20.9
Access or Improved Road	In Progress	2	2.1
Access or Improved Road	In Use - Fire Management	3	0.7
Access or Improved Road	No Repair Needed	300	141
Access or Improved Road	Other - See Comments	3	0.1
Access or Improved Road	Repair Needed	8	6.1
Access or Improved Road	Unknown	44	4.4
Completed Burnout	Completed - Inspected	1	1.6
Completed Dozer Line	Completed - Inspected	179	78
Completed Dozer Line	Completed - Ready for Inspection	3	0.1
Completed Dozer Line	In Progress	41	20.7
Completed Dozer Line	In Use - Fire Management	5	1.3
Completed Dozer Line	No Repair Needed	39	10.1
Completed Dozer Line	Other - See Comments	2	0.5
Completed Dozer Line	Repair Needed	105	29.6
Completed Dozer Line	Unknown	8	1.2
Completed Fuel Break	Completed - Inspected	5	2
Completed Fuel Break	No Repair Needed	2	1.3
Completed Hand Line	Completed - Inspected	66	15.4
Completed Hand Line	Completed - Ready for Inspection	9	2
Completed Hand Line	In Progress	4	0.4
Completed Hand Line	In Use - Fire Management	3	0.7
Completed Hand Line	No Repair Needed	50	10.7
Completed Hand Line	Repair Needed	53	16.9
Completed Hand Line	Unknown	9	4.6
Completed Mixed Construction Line	Completed - Inspected	10	3.8
Completed Mixed Construction Line	In Progress	2	1.6
Completed Mixed Construction Line	In Use - Fire Management	1	0.2
Completed Mixed Construction Line	No Repair Needed	7	1.9
Completed Mixed Construction Line	Other - See Comments	2	0.6
Completed Mixed Construction Line	Repair Needed	11	5.9
Completed Plow Line	Completed - Inspected	1	0.3
Completed Road as Line	Completed - Inspected	42	42.5
Completed Road as Line	In Progress	10	5.1
Completed Road as Line	No Repair Needed	44	39.2
Completed Road as Line	Other - See Comments	3	1
Completed Road as Line	Repair Needed	34	22.5
Completed Road as Line	Unknown	14	2.1
Contained Line	No Repair Needed	3	206.3
Contained Line	Repair Needed	1	3.2
Contained Line	Unknown	109	145
Fire Edge	Unknown	115	89.4
Planned Dozer Line	Unknown	16	18.5
Planned Hand Line	Completed - Inspected	2	0.7
Planned Hand Line	In Progress	1	0.1
Planned Hand Line	No Repair Needed	1	0.4
Planned Hand Line	Unknown	8	5.2
Planned Mixed Construction Line	No Repair Needed	1	0.2
Planned Mixed Construction Line	Unknown	4	7.7
Planned Road as Line	Completed - Inspected	1	0.1
Planned Road as Line	In Progress	1	1
Planned Road as Line	No Repair Needed	3	1.8
Planned Road as Line	Unknown	10	27
Repair Line	Completed - Inspected	1	0.6
Retardant Drop	Completed - Inspected	1	0.1
Retardant Drop	No Repair Needed	5	1.1
Retardant Drop	Unknown	1	0.1

Div K
Div L
Div M
Div N
Div O
Div Q
Div R
Div S
Div T
Div U

SAWYERS BAR RAWS
BLUE RIDGE RAWS
Ceciville RAWS
IRAWS 3 (Eddy Gulch LO)
CALAHAN RAWS
Callahan
C-85
C-11
C-31
C-86
C-112
C-97
Water Tank
Carter Check
Tangle Blue Spike H
Bluff Spike
Mule Sling
Smart Pump Sling
NO DIP
Trinity
SCORPION RAWS
COFFEE CREEK RANCH
TYPE 6 ONLY
Coffee
Boulder Lake TH
Boulder
NORTH SLING
Road End
Site 14
Sling 15
LAKE ELEANOR TRAWS
Road Washout
Tower 11

KLAMATH NATIONAL FOREST
SHASTA NATIONAL FOREST
TRINITY NATIONAL FOREST
Marble Mountains Wilderness
Russian Wilderness
Trinity Alps Wilderness
SISKIYOU CO.
TRINITY CO.
SHASTA CO.

In Progress
Fire Edge
Contained Line
Completed Burnout
Completed Dozer Line
Completed Fuel Break
Completed Hand Line
Completed Mixed Construction Line
Completed Plow Line
Completed Road as Line
Planned Dozer Line
Planned Hand Line
Planned Mixed Construction Line
Planned Road as Line
Access or Improved Road
Repair Line
Retardant Drop
Aerial Hazard
Check Point
Helispot
Helibase
Sling Site
Division Break
Drop Point
Closure
Camp
Staging Area
Lookout
Hot Spot - Spot Fire
Value at Risk
Other
Landmark
Gate
Bridge
Water Development or Draft Site
Structure Wrap
Stream Crossing
Road Repair
Resource Location
Repair Point
Landing or Log Deck
Hazard Tree
Dozer Push
Culvert
Clean Up Area
Mobile Weather Unit
Internet Access
Repeater
Hazard
Water Source
Restricted Water Source
Other Property
Pump
Water Tank
In Progress
Section Protracted
Section
Private Timberland

Suppression Repair

River Complex
CA-KNF-006385
10/13/2021 07:00

Nevada Type 3 Incident Management Team

0 1 2 3 4 5 Miles

1:63,786