



Feature/Category	Repair/Status	FREQUENCY	Sum_Length/Count
Access or Improved Road	Completed - Inspected	2	11123
Access or Improved Road	In Progress	2	11123
Access or Improved Road	No Repair Needed	207	94577
Access or Improved Road	Other - See Comments	1	11123
Access or Improved Road	Repair Needed	5	14987
Completed Burned	No Repair Needed	1	9573
Completed Dozer Line	Completed - Inspected	546	57954
Completed Dozer Line	Completed - Ready for Inspection	1	75
Completed Dozer Line	In Progress	23	9173
Completed Dozer Line	Other - Fire Management	1	24
Completed Dozer Line	No Repair Needed	41	5749
Completed Dozer Line	Other - See Comments	2	149
Completed Dozer Line	Repair Needed	56	6483
Completed Dozer Line	Unknown	2	149
Completed Fuel Break	Completed - Inspected	5	5233
Completed Fuel Break	No Repair Needed	2	9573
Completed Hand Line	Completed - Inspected	99	14574
Completed Hand Line	Completed - Ready for Inspection	1	103
Completed Hand Line	In Progress	2	149
Completed Hand Line	On Use - Fire Management	3	9251
Completed Hand Line	No Repair Needed	16	14574
Completed Hand Line	Repair Needed	29	13321
Completed Hand Line	Unknown	1	149
Completed Mixed Construction Line	Completed - Inspected	15	9573
Completed Mixed Construction Line	On Use - Fire Management	1	957
Completed Mixed Construction Line	No Repair Needed	2	149
Completed Mixed Construction Line	Other - See Comments	2	207
Completed Mixed Construction Line	Repair Needed	8	14574
Completed Flow Line	Completed - Inspected	1	149
Completed Road as Line	Completed - Inspected	66	14574
Completed Road as Line	No Repair Needed	49	10251
Completed Road as Line	Other - See Comments	17	9574
Completed Road as Line	Unknown	11	1063
Completed Line	No Repair Needed	112	14574
Completed Line	Unknown	1	149
Fire Edge	No Repair Needed	12	24867
Fire Edge	Unknown	4	256
Planned Hand Line	No Repair Needed	16	14574
Planned Hand Line	Repair Needed	11	2575
Planned Mixed Construction Line	No Repair Needed	15	14574
Planned Mixed Construction Line	Repair Needed	1	149
Retardant Drop	Completed - Inspected	1	1152
Retardant Drop	Completed - Inspected	1	149
Retardant Drop	No Repair Needed	7	14521

Completed - Inspected	Fire Edge	Completed Mixed Construction Line	R - Planned Road as Line	Pump	Other - See Comments
In Use - Fire Management	Contained Line	R - Completed Road as Line	Access or Improved Road	Water Tank	Unknown
In Progress	Completed Dozer Line	Completed Fuel Break	Planned Hand Line	Completed - Inspected	Section Protracted
Repair Needed	Completed Fuel Break	Completed Hand Line	Planned Mixed Construction Line	In Progress	Section
No Repair Needed	Completed Hand Line	Drop Point	Private Timberland	Repair Needed	Forest Service
Other - See Comments	Completed Hand Line			No Repair Needed	

Suppression Repair
 River Complex
 CA-KNF-006385
 10/17/2021 07:00

Scale: 0 1 2 Miles
 1:28,500