



- Dip Site
- Hotspot
- | Division Break
- | Branch Break
- | Incident Command Post
- | Drop Point
- | Closure
- | Staging Area
- | Lookout
- | Value at Risk
- | Other
- | Landmark
- | Bridge
- | Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Repair Point
- Hazard Tree
- Fence - Cut/Damaged
- Dozer Push
- Culvert
- Clean Up Area
- Repeater
- Safety Zone
- Water Source
- | Completed Dozer Line
- | Completed Hand Line
- | Completed Mixed Construction Line
- | Retardant in Avoidance Area
- | Highlighted Feature
- | Other
- | Repair Line
- | Road Repair
- | Dozer Push
- | Contained Line
- | PG&E Transmission Lines
- | PG&E Gas Lines
- | USFS Wilderness
- | Tactical Ridgetop Repair Needed
- | Repair Status Point
- | Completed - Inspected
- | In Use - Fire Management
- | Completed - Ready for Inspection
- | In Progress
- | Repair Needed
- | No Repair Needed
- | Other - See Comments
- | Unknown
- | Repair Status Line
- | Completed - Inspected
- | Completed - Ready for Inspection
- | In Progress
- | Repair Needed
- | No Repair Needed
- | Other - See Comments
- | Unknown
- | Direct Protection Area
- | California Department of Forestry and Fire Protection
- | USDA Forest Service
- | Ownership
- | Bureau of Indian Affairs
- | Bureau of Land Management
- | Private
- | Sierra Pacific Industries
- | USDA Forest Service

# SUPPRESSION REPAIR

MCFARLAND  
CA-SHF-001175  
8/29/2021

