


Repair Status	
● Completed - Inspected	▬ Completed - Inspected
● Completed - Ready for Inspection	▬ Completed - Ready for Inspection
● In Progress	▬ In Progress
● Repair Needed	▬ Repair Needed
● No Repair Needed	▬ No Repair Needed
● Other - See Comments	▬ Other - See Comments
● Unknown	▬ Unknown

	Check Point		Dip Site		Mobile Retardant Base		Helibase		Division Break		Branch Break		Drop Point		Camp		Lookout		Value at Risk																														
	Other		Gate		Water Development or Draft Site		Stream Crossing		Road Repair		Retardant in Avoidance Area		Resource Location		Repair Point		Landing or Log Deck		Dozer Push		Culvert		Road Repair		Mobile Weather Unit																								
	Internet Access		Repeater		Hazard		Water Source		Completed Dozer Line		Completed Hand Line		Completed Mixed Construction Line		Completed Road as Line		Access or Improved Road		Other		Repair Line		Road Repair		Retardant Drop		Fire Edge		Contained Line		NON-FS		USDA FOREST SERVICE		Forest Boundary		BLM		Wilderness		National Wild and Scenic River		County Boundary		DPA		Federal		State



SUPPRESSION REPAIR
MONUMENT
CA-SHF-001187
08/17/2021



Suppression Repair
Monument
CA-SHF-001187
08/17/2021