



**Repair Status**

<span style="color: green;">●</span> Completed - Inspected	<span style="color: green;">▬</span> Completed - Inspected
<span style="color: orange;">●</span> Completed - Ready for Inspection	<span style="color: orange;">▬</span> Completed - Ready for Inspection
<span style="color: yellow;">●</span> In Progress	<span style="color: yellow;">▬</span> In Progress
<span style="color: red;">●</span> Repair Needed	<span style="color: red;">▬</span> Repair Needed
<span style="color: grey;">●</span> No Repair Needed	<span style="color: grey;">▬</span> No Repair Needed
<span style="color: blue;">●</span> Other - See Comments	<span style="color: blue;">▬</span> Other - See Comments
<span style="color: purple;">●</span> Unknown	<span style="color: purple;">▬</span> Unknown

Check Point	Gate	Internet Access	R - R Planned Road as Line
Dip Site	Stream Crossing	Safety Zone	Access or Improved Road
Heliport	Road Repair	Water Source	Other
Division Break	Retardant in Avoidance Area	Completed Burnout	Road Repair
Branch Break	Repair Point	Completed Dozer Line	Retardant Drop
Drop Point	Landing or Log Deck	Completed Fuel Break	Fire Edge
Camp	Hazard Tree	Completed Hand Line	Contained Line
Staging Area	Fence - Cut/Damaged	Completed Mixed Construction Line	NON-FS
Value at Risk	Dozer Push	R - R Completed Road as Line	USDA FOREST SERVICE
Other	Culvert	Planned Dozer Line	Forest Boundary
	Clean Up Area	Planned Hand Line	BLM
	Mobile Weather Unit	Planned Mixed Construction Line	Wilderness

N  
W    E  
S

NAD 1983 UTM Zone 10N

0    0.5    1    2 Miles

Scale: 1:24,193 (1 inch equals 0 mile)

## SUPPRESSION REPAIR

### BRANCH 30

MONUMENT  
CA-SRF-000795  
09/25/2021



FOREST SERVICE  
DEPARTMENT OF AGRICULTURE

Regional Incident Management Team

Northern Rockies  
INCIDENT MANAGEMENT TEAM

**Suppression Repair**  
Monument  
CA-SRF-000795  
09/25/2021