


Repair Status	
<span style="color: green;">●</span>	Completed - Inspected
<span style="color: orange;">●</span>	Completed - Ready for Inspection
<span style="color: yellow;">●</span>	In Progress
<span style="color: red;">●</span>	Repair Needed
<span style="color: grey;">●</span>	No Repair Needed
<span style="color: blue;">●</span>	Other - See Comments
<span style="color: purple;">●</span>	Unknown

**Suppression Repair**  
**Monument**  
**CA-SRF-000795**  
**09/25/2021**

- Aerial Hazard
- Airstrip or Airport
- Check Point
- Dip Site
- Mobile Retardant Base
- Helipad
- Hobase
- Unimproved Landing Area
- Division Break
- Branch Break
- Drop Point
- Camp
- Staging Area
- Lookout
- Hot Spot - Spot Fire
- Value at Risk
- Other
- Fire Station
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Fence - Cut/Damaged
- Dicer Push
- Gate
- Clean Up Area
- Mobile Weather Unit
- Internet Access
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Hazard
- Water Source
- Restricted Water Source
- Completed Burnout
- Completed Dzer Line
- Completed Fuel Break
- M - M Completed Hand Line
- M - H Completed Mixed Construction Line
- Planned Dzer Line
- Planned Hand Line
- Planned Mixed Construction Line
- Planned Road as Line
- Access or Improved Road
- Fence
- Other
- Repair Line
- Road Repair
- Retardant Drop
- Confined Line
- HONFA
- USDA FOREST SERVICE
- Forest Boundary
- BLM
- Wilderness
- National Wild and Scenic River



NAD 1983 UTM Zone 10N  
 Scale: 1:70,889 (1 inch equals 1 mile)

# SUPPRESSION REPAIR

## OVERVIEW

**MONUMENT**  
**CA-SRF-000795**  
**09/25/2021**



**Suppression Repair**  
**Monument**  
**CA-SRF-000795**  
**09/25/2021**