


Suppression Repair
Branch XX
 McCash
 CA-SRF-000651
 Sept 29, 2021
 93,244 acres
 as of 9/26/2021, 1945 Hrs



- | | | | | | | | |
|--|--|--|--|--|--|--|---|
| ● Completed - Inspected | P Other Property | S Incident Command Post | ■ Stream Crossing | R Repeater | Access or Improved Road | Road - Light Duty - Dirt | Wildfire Daily Fire Perimeter |
| ● Completed - Ready for Inspection | W Water Tank | S Staging Area | ■ Road Repair | H Hazard | Repair Line | Road - Light Duty - Gravel | Private land |
| ● In Progress | U Helispot | S Value at Risk | ■ Repair Point | W Restricted Water Source | Retardant Drop | Road - Light Duty - Paved | Bureau of Land Management (BLM) |
| ● Repair Needed | D Dip Site | O Other | ■ Landing or Log Deck | C Completed Burnout | Contained Line | Road - Light Duty - Unknown | State |
| ● No Repair Needed | U Unimproved Landing Area | G Gate | ■ Dozer Push | C Completed Dozer Line | Footbridge | Road - Unimproved | Bureau of Indian Affairs (BIA) |
| ● Other - See Comments | D Drop Point | B Bridge | ■ Culvert | H Completed Hand Line | Trail | Trail - Nat Rec/Scenic/Historic | USFS Wilderness |
| ● Unknown | | W Structure Wrap | ■ Mobile Water Unit | R Completed Road as Line | Highway | | |



NAD 1983 UTM Zone 10N
 AK Team
 9/28/2021, 2326hrs