



Suppression Repair
Div J/N
 McCash CA-SRF-000651
 Sept 29, 2021
 93,244 acres as of 9/26/2021, 1945 Hrs



Completed - Ready for Inspection	Other Property	Unimproved Landing Area	Other	Road Repair	Culvert	Completed Burnout	R - R - Completed Road as Line	Contained Line	Wildfire Daily Fire Perimeter
In Progress	Pump	Drop Point	Gate	Resource Location	Mobile Weather Unit	Completed Dozer Line	Access or Improved Road	Footbridge	Private land
Repair Needed	Water Tank	Staging Area	Bridge	Repair Point	Repeater	Completed Fuel Break	Repair Line	Road - Light Duty - Unknown	Bureau of Land Management (BLM)
No Repair Needed	Helispot	Dip Site	Structure Wrap	Hazard Tree	Hazard	Retardant Drop	Fire Edge	Road - Unimproved	Bureau of Indian Affairs (BIA)
Unknown	Value at Risk		Stream Crossing	Dozer Push	Restricted Water Source	Trail	Road - Light Duty - Gravel	Trail - Nat Rec/Scenic/Historic	USFS Wilderness

N

 Mobile Maps
 NAD 1983 UTM Zone 10N
 AK Team 1 9/28/2021, 2327hrs
 0 0.5 1 2 Miles