


Suppression Repair
 McCash CA-SRF-000651
 Sept 29, 2021
 93,244 acres as of 9/26/2021, 1945 Hrs



● Completed - Inspected	Water Tank	Gate	Hazard Tree	Completed Fuel Break	Footbridge	Wildfire Daily Fire Perimeter
● Completed - Ready for Inspection	Dip Site	Bridge	Dozer Push	Completed Hand Line	Highway	Private land
● In Progress	Unimproved Landing Area	Structure Wrap	Culvert	Completed Mixed Construction Line	Road - Light Duty - Dirt	Bureau of Land Management (BLM)
● Repair Needed	Drop Point	Stream Crossing	Mobile Weather Unit	Completed Road as Line	Road - Light Duty - Gravel	State
● No Repair Needed	Incident Command Post	Road Repair	Repeater	Access or Improved Road	Road - Light Duty - Paved	Bureau of Indian Affairs (BIA)
● Other - See Comments	Camp	Resource Location	Hazard	Repair Line	Road - Light Duty - Unknown	USFS Wilderness
● Unknown	Staging Area	Repair Point	Restricted Water Source	Retardant Drop	Trail - Unimproved	
Other Property	Pump	Landing or Log Deck	Completed Burnout	Fire Edge	Trail - Improved	
Value at Risk			Completed Dozer Line	Contained Line	Trail - Nat Rec/Scenic/Historic	



NAD 1983 UTM Zone 10N
 AK Team 1
 9/28/2021, 2328hrs