


Suppression Repair
Branch X
 McCash
 CA-SRF-000651
 Sept 30, 2021
 93,244 acres
 as of 9/29/2021, 1915 Hrs



● Completed - Inspected	P Other Property	● Helispot	G Gate	➡ Dozer Push	 Completed Dozer Line	 Retardant Drop	 Road - Light Duty - Paved	 Bureau of Land Management (BLM)
● Completed - Ready for Inspection	W Water Tank	● Dip Site	B Bridge	➡ Culvert	 Completed Fuel Break	 Fire Edge	 Road - Light Duty - Unknown	 Bureau of Indian Affairs (BIA)
● In Progress	S Staging Area	● Drop Point	S Structure Wrap	➡ Mobile Weather Unit	 Completed Hand Line	 Contained Line	 Road - Unimproved	 USFS Wilderness
● Repair Needed	V Value at Risk	● Camp	C Stream Crossing	➡ Repeater	 Completed Mixed Construction Line	 Footbridge	 Trail	
● No Repair Needed	O Other - See Comments	● Road Repair	R Road Repair	⚠ Hazard	 Completed Road as Line	 Highway	 Trail - Nat Rec/Scenic/Historic	
● Other - See Comments	I Other	➡ Resource Location	R Resource Location	W Restricted Water Source	 Access or Improved Road	 Road - Light Duty - Dirt	 Trail - Nat Rec/Scenic/Historic	
● Unknown		➡ Repair Point	R Repair Point	B Completed Burnout	 Repair Line	 Road - Light Duty - Gravel	 Wildfire Daily Fire Perimeter	
							 Private land	



NAD 1983 UTM Zone 10N
 AK Team 1
 9/29/2021, 2345hrs