



Suppression Repair
 McCash CA-SRF-000651
 Oct 1, 2021
 93,514 acres as of 9/29/2021, 1915 Hrs



- | | | | | | | |
|--|-----------------------|---------------------|-------------------------|-----------------------------------|---------------------------------|---------------------------------|
| ● Completed - Inspected | Water Tank | Gate | Dozer Push | Completed Hand Line | Highway | Private land |
| ● Completed - Ready for Inspection | Helispot | Bridge | Culvert | Completed Mixed Construction Line | Road - Light Duty - Dirt | Bureau of Land Management (BLM) |
| ● In Progress | Dip Site | Structure Wrap | Mobile Weather Unit | Completed Road as Line | Road - Light Duty - Gravel | State |
| ● Repair Needed | Drop Point | Stream Crossing | Repeater | Access or Improved Road | Road - Light Duty - Paved | Bureau of Indian Affairs (BIA) |
| ● No Repair Needed | Incident Command Post | Road Repair | Hazard | Repair Line | Road - Light Duty - Unknown | USFS Wilderness |
| ● Other - See Comments | Camp | Resource Location | Restricted Water Source | Retardant Drop | Road - Unimproved | |
| ● Unknown | Staging Area | Repair Point | Completed Burnout | Fire Edge | Trail | |
| ● Other Property | Other Property | Landing or Log Deck | Completed Dozer Line | Contained Line | Trail - Nat Rec/Scenic/Historic | |
| Pump | Value at Risk | Hazard Tree | Completed Fuel Break | Footbridge | Wildfire Daily Fire Perimeter | |
| | Other | | | | | |

0 0.5 1 2 Miles
 NAD 1983 UTM Zone 10N
 AK Team 1
 9/30/2021, 2200hrs