



Suppression Repair
South
 McCash
 CA-SRF-000651
 October 3, 2021
 93,514 acres
 as of 9/30/2021, 1915 Hrs



- | | | | | | | | |
|------------------------------------|-------------------------|-------------------|-----------------------|----------------------------------|----------------------------|-----------------------------------|-----------------------------------|
| ● Completed - Inspected | ■ Other Property | ■ Staging Area | ● Road Repair | ⚠ Hazard | — Repair Line | — Road - Light Duty - Gravel | ■ Private land |
| ● Completed - Ready for Inspection | ■ Pump | ⚠ Value at Risk | ● Repair Point | ⚠ Restricted Water Source | — Retardant Drop | — Road - Light Duty - Paved | ■ Bureau of Land Management (BLM) |
| ● In Progress | ■ Water Tank | ■ Gate | ● Landing or Log Deck | ⚠ Completed Burnout | — Fire Edge | — Road - Light Duty - Unknown | ■ State |
| ● Repair Needed | ■ Helispot | ■ Bridge | ● Dozer Push | ⚠ Completed Dozer Line | — Contained Line | — Road - Unimproved | ■ Bureau of Indian Affairs (BIA) |
| ● No Repair Needed | ■ Dip Site | ■ Structure Wrap | ● Culvert | — H - H - Completed Hand Line | — Footbridge | — Trail | ■ USFS Wilderness |
| ● Other - See Comments | ■ Drop Point | ■ Stream Crossing | ● Mobile Weather Unit | — R - R - Completed Road as Line | — Highway | — Trail - Nat Rec/Scenic/Historic | |
| ● Unknown | ■ Incident Command Post | | ● Repeater | — Access or Improved Road | — Road - Light Duty - Dirt | — Wildlife Daily Fire Perimeter | |



N
 0 0.5 1 2 Miles
 NAD 1983 UTM Zone 10N
 AK Team
 10/2/2021, 230hrs