



Suppression Repair
Div J/N
 McCash CA-SRF-00651
 October 7, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs



Completed - Inspected	Unknown	Dip Site	Value at Risk	Stream Crossing	Dozer Push	Restricted Water Source	Completed Mixed Construction Line	Fire Edge	Road - Light Duty - Gravel	Trail - Nat Rec/Scenic/Historic	Wildfire Daily Fire Perimeter
Completed - Ready for Inspection	Other Property	Drop Point	Other	Road Repair	Culvert	Completed Burnout	Completed Road as Line	Contained Line	Road - Light Duty - Paved	Private land	
In Progress	Pump	Incident Command Post	Gate	Resource Location	Mobile Weather Unit	Completed Dozer Line	Access or Improved Road	Footbridge	Road - Light Duty - Unknown	Bureau of Land Management (BLM)	
Repair Needed	Water Tank	Camp	Bridge	Repair Point	Repeater	Completed Fuel Break	Repair Line	Highway	Road - Unimproved	Bureau of Indian Affairs (BIA)	
No Repair Needed	Hellsite	Staging Area	Structure Wrap	Hazard Tree	Hazard	Completed Hand Line	Retardant Drop	Road - Light Duty - Dirt	Trail		

N

 Mobile Maps
 NAD 1983 UTM Zone 10N
 AK Team 1 10/6/2021, 2130hrs
 0 0.5 1 2 Miles