



Suppression Repair
North
McCash
 CA-SRF-000651
 October 7, 2021
 94,962 acres
 as of 9/30/2021, 1915 Hrs



- | | | | | | | | |
|------------------------------------|-------------------------|-------------------------|---------------------|-----------------------|-------------------------------------|---------------------------|-------------------------------|
| ● Completed - Inspected | Ⓟ Pump | ● Hellsport | ⊙ Other | ⬆ Repair Point | ⚠ Hazard | ⋯ Completed Road as Line | — Highway |
| ● Completed - Ready for Inspection | Ⓜ Water Tank | ● Dip Site | Ⓜ Gate | ⬆ Landing or Log Deck | ⚠ Restricted Water Source | — Access or Improved Road | — Road - Light Duty - Dirt |
| ● In Progress | Ⓜ Incident Command Post | ● Drop Point | Ⓜ Bridge | ⬆ Dozer Tree | Ⓜ Completed Burnout | — Repair Line | — Road - Light Duty - Gravel |
| ● Repair Needed | Ⓜ Camp | ● Incident Command Post | Ⓜ Structure Wrap | ⬆ Culvert | Ⓜ Completed Dozer Line | — Retardant Drop | — Road - Light Duty - Paved |
| ● No Repair Needed | Ⓜ Staging Area | ● Camp | Ⓜ Stream Crossing | ⬆ Mobile Weather Unit | Ⓜ Completed Fuel Break | — Fire Edge | — Road - Light Duty - Unknown |
| ● Unknown | Ⓜ Value at Risk | Ⓜ Staging Area | Ⓜ Road Repair | Ⓜ Repeater | Ⓜ Completed Hand Line | — Contained Line | — Road - Unimproved |
| ● Other Property | | Ⓜ Staging Area | Ⓜ Resource Location | | Ⓜ Completed Mixed Construction Line | — Footbridge | — Trail |

⋯ Trail - Nat Rec/Scenic/Historic	— Wildfire Daily Fire Perimeter
— Private land	— Bureau of Land Management (BLM)
— Bureau of Indian Affairs (BIA)	— USFS Wilderness

NAD 1983 UTM Zone 10N
 AK Team 1
 10/6/2021, 2124hrs