



Suppression Repair
South
 McCash
 CA-SRF-000651
 October 7, 2021
 94,962 acres
 as of 9/30/2021, 1915 Hrs



- | | | | | | | | |
|--------------------|-----------------|-----------------------|---------------------------|----------------------------------|-------------------------------|-----------------------------------|-------------------|
| ● Repair Needed | ○ Dip Site | 🏠 Structure Wrap | 🚧 Culvert | — · — · — · Completed Hand Line | — Footbridge | ⋯ Trail | 🌿 USFS Wilderness |
| ○ No Repair Needed | ⬇ Drop Point | 🌳 Stream Crossing | 🚚 Mobile Weather Unit | — R - R - Completed Road as Line | — Highway | ⋯ Trail - Nat Rec/Scenic/Historic | |
| ⬇ Unknown | 📍 Staging Area | 🔧 Road Repair | 🔧 Repeater | — Access or Improved Road | — Road - Light Duty - Dirt | — Wildfire Daily Fire Perimeter | |
| ⬇ Other Property | ⚠ Value at Risk | 🔧 Repair Point | ⚠ Hazard | — Repair Line | — Road - Light Duty - Gravel | 🏠 Private land | |
| 📍 Pump | ⬇ Other | 🏠 Landing or Log Deck | 🚰 Restricted Water Source | — Retardant Drop | — Road - Light Duty - Paved | 🏠 Bureau of Land Management (BLM) | |
| 📍 Water Tank | ⬇ Gate | 🌳 Hazard Tree | 🚧 Completed Burnout | — Fire Edge | — Road - Light Duty - Unknown | 🏠 State | |
| 📍 Heliport | 🚧 Bridge | 🚧 Dozer Push | 🚧 Completed Dozer Line | — Contained Line | ⋯ Road - Unimproved | 🏠 Bureau of Indian Affairs (BIA) | |



N

0 0.5 1 2 Miles

NAD 1983 UTM Zone 10N
 AK Team 1
 10/6/2021, 2129hrs