



Suppression Repair
 McCash CA-SRF-000651
 October 9, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs



- Repair Status**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown

- Other Property
- P Pump
- W Water Tank
- H Helipost
- D Dip Site
- U Unimproved Landing Area
- | Division Break
- D Drop Point
- I Incident Command Post
- A Camp
- S Staging Area
- V Value at Risk
- O Other
- G Gate
- B Bridge
- W Water Development or Draft Site
- S Structure Wrap
- C Stream Crossing

- R Road Repair
- P Repair Point
- L Landing or Log Deck
- H Hazard Tree
- D Dozer Push
- C Culvert
- W Water Source
- R Restricted Water Source
- C Completed Dozer Line

- M Completed Fuel Break
- H Completed Hand Line
- M Completed Mixed Construction Line
- R Completed Road as Line
- O Other
- R Repair Line
- F Fire Edge
- C Contained Line
- F Footbridge

- H Highway
- R Road - Light Duty - Dirt
- R Road - Light Duty - Gravel
- R Road - Light Duty - Paved
- R Road - Light Duty - Unknown
- R Road - Unimproved
- T Trail
- T Trail - Nat Rec/Scenic/Historic

- Bureau of Land Management (BLM)
- State
- Bureau of Indian Affairs (BIA)
- Private land
- USFS Wilderness



NAD 1983 UTM Zone 10N
 108/2021, 2138hrs