



**Suppression Repair**  
**Div J/N**  
 McCash CA-SRF-000651  
 October 9, 2021  
 94,962 acres as of 9/30/2021, 1915 Hrs



- Repair Status**
- Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown

- Other Property
- P Pump
- W Water Tank
- Helispot
- X Dip Site
- S Staging Area
- D Drop Point
- I Incident Command Post
- C Camp
- V Value at Risk
- O Other
- G Gate
- B Bridge
- W Water Development or Draft Site
- S Structure Wrap
- A Stream Crossing
- R Road Repair
- P Repair Point
- T Hazard Tree
- D Dozer Push
- C Culvert
- W Water Source
- R Restricted Water Source
- X Completed Dozer Line
- W Completed Fuel Break
- H Completed Hand Line
- M Completed Mixed Construction Line
- R Completed Road as Line
- Other
- Repair Line
- Fire Edge
- Contained Line
- Footbridge
- Road - Unimproved
- Road - Light Duty - Dirt
- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown
- Trail
- Trail - Nat Rec/Scenic/Historic
- Bureau of Indian Affairs (BIA)
- USFS Wilderness
- Private land
- Bureau of Land Management (BLM)

N  
  
  
 Mobile Maps  
 NAD 1983 UTM Zone 10N  
 AK Team 1 10/8/2021, 2133hrs  
 0 0.5 1 2 Miles