



Suppression Repair
Div J/N
 McCash CA-SRF-000651
 October 11, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs



- Repair Status**
- Completed - Inspected
 - In Use - Fire Management
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown

- P Other Property
- P Pump
- W Water Tank
- W Dip Site
- S Staging Area
-) Division Break
- D Drop Point
- I Incident Command Post
- C Camp
- V Value at Risk
- O Other
- G Gate
- B Bridge
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Repair Point
- Hazard Tree
- Dozer Push
- Culvert
- Water Source
- Restricted Water Source
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Other
- Repair Line
- Fire Edge
- Contained Line
- Footbridge
- Road - Unimproved
- Trail
- Trail - Nat Rec/Scenic/Historic
- Road - Light Duty - Dirt
- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown
- Bureau of Indian Affairs (BIA)
- USFS Wilderness
- Private land
- Bureau of Land Management (BLM)

N

 Mobile Maps
 NAD 1983 UTM Zone 10N
 AK Team 1 10/11/2021, 0022hrs
 0 0.5 1 2 Miles