



Suppression Repair
Div D
 McCash CA-SRF-000651
 Oct 20, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs



- Repair Status**
- Completed: Stage 1 & 2 Completed
 - Completed: Ready for Inspection
 - Repair Needed
 - No Repair Needed
 - Other: See Comments
 - Unknown

- Helispot
- Drop Point
- Staging Area
- Value at Risk
- Other
- Gate
- Bridge
- Stream Crossing
- Road Repair

- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Culvert
- Mobile Weather Unit
- Repeater
- Hazard

- Completed Dozer Line
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Other
- Repair Line
- Contained Line
- Highway
- Road - Light Duty - Dirt

- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown
- Road - Unimproved
- Trail
- Trail - Nat Rec/Scenic/Historic
- Private land
- USFS Wilderness

NAD 1983 UTM Zone 10N
 G.T. Type 3
 10/19/2021, 2253hrs

0 0.25 0.5 1 Miles