

Suppression Repair
 McCash CA-SRF-000651
 Oct 20, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs

- Repair Status**
- Completed: Stage 1 & 2 Completed
 - Completed: Ready for Inspection
 - Repair Needed
 - No Repair Needed
 - Other: See Comments
 - Unknown

- Helispot
- Drop Point
- ▲ Incident Command Post
- S Camp
- S Staging Area
- ! Value at Risk
- Other

- ⬮ Gate
- ⬮ Bridge
- ⬮ Structure Wrap
- ⬮ Stream Crossing
- ⬮ Road Repair
- ⬮ Resource Location
- ⬮ Repair Point


- ⬮ Landing or Log Deck
- ⬮ Hazard Tree
- ⬮ Dozer Push
- ⬮ Culvert
- ⬮ Mobile Weather Unit
- ⬮ Repeater
- ⬮ Hazard

- ⬮ Completed Dozer Line
- ⬮ Completed Fuel Break
- ⬮ Completed Hand Line
- ⬮ Completed Mixed Construction Line
- ⬮ Completed Road as Line
- ⬮ Other
- ⬮ Repair Line

- ⬮ Fire Edge
- ⬮ Contained Line
- ⬮ Footbridge
- ⬮ Highway
- ⬮ Road - Light Duty - Dirt
- ⬮ Road - Light Duty - Gravel
- ⬮ Road - Light Duty - Paved

- ⬮ Road - Light Duty - Unknown
- ⬮ Road - Unimproved
- ⬮ Trail
- ⬮ Trail - Nat Rec/Scenic/Historic
- ⬮ Bureau of Land Management (BLM)
- ⬮ State
- ⬮ Bureau of Indian Affairs (BIA)

- Private land
- USFS Wilderness



NAD 1983 UTM Zone 10N
 G.T. Type 3
 10/19/2021, 2253hrs