Suppression Repair South

McCash

CA-SRF-000651

Oct 24, 2021

94,962 acres

as of 9/30/2021, 1915 Hrs

Div D

Div Q

Div T

South

Cottage Grove

CMPLX Ukonom Mt. Lookout + 1 P-RAWS 15

Ti Bar

Dillon Mountain

Patterson

SRF52

Marble Mountain Ranch

Rogers Creek

Somes Bar

Oakbottom

Orleans

Wooley Creek

Steinacher Ridge

Campbell (River Complex)

Island (River Complex)

Speciman (River Complex)

Kelly (River Complex)

Cronan (River Complex)

MARBLE MOUNTAINS

SALMON MOUNTAINS

SCOTT MOUNTAINS

KLAMATH MOUNTAINS

Repair Status

- Completed: Stage 1 & 2 Completed
- Completed: Ready for Inspection
- In Progress: Stage 2 Needed
- Repair Needed
- In Use: Fire Management
- No Repair Needed
- Other: See Comments

- Unknown
- Helispot
- Drop Point
- Staging Area
- Value at Risk
- Other

- Gate
- Bridge
- Structure Wrap
- Stream Crossing
- Road Repair
- Repair Point

- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Culvert
- Clean Up Area
- Mobile Weather Unit

- Repeater
- Hazard
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Other

- Repair Line
- Fire Edge
- Contained Line
- Footbridge
- Highway
- Road - Light Duty - Dirt

- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown
- Road - Unimproved
- Trail
- Trail - Nat Rec/Scenic/Historic

- Private land
- Bureau of Land Management (BLM)
- State
- Bureau of Indian Affairs (BIA)
- USFS Wilderness

N

Mobile Maps

0 0.5 1 2 Miles

NAD 1983 UTM Zone 10N
G.T. Type 3
10/23/2021, 2318hrs