



Suppression Repair

Div T
 McCash CA-SRF-000651
 Oct 27, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs

- Repair Status**
- Completed: Stage 1 & 2 Completed
 - Repair Needed
 - No Repair Needed
 - Unknown
 - Helispot
 - Drop Point

- S Staging Area
- ⬇ Value at Risk
- ⬇ Other
- ⬇ Gate
- ⬇ Bridge
- ⬇ Structure Wrap
- ⬇ Road Repair
- ⬇ Repair Point
- ⬆ Landing or Log Deck
- ⬆ Hazard Tree
- ⬆ Dozer Push
- ⬆ Culvert
- ⬆ Clean Up Area
- ⬆ Mobile Weather Unit
- ⬆ Repeater
- ⬆ Hazard
- ⊗ Completed Dozer Line
- H - Completed Hand Line
- R - Completed Road as Line
- Other
- Repair Line
- Contained Line
- Footbridge
- Highway

- Road - Light Duty - Dirt
- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown
- Road - Unimproved
- Trail
- Private land
- Bureau of Land Management (BLM)

- Bureau of Indian Affairs (BIA)
- USFS Wilderness



NAD 1983 UTM Zone 10N
 G.T. Type 3
 10/26/2021, 2247hrs
 0 0.25 0.5 1 Miles