


Suppression Repair
 McCash CA-SRF-000651
 October 28, 2021
 94,962 acres as of 9/30/2021, 1915 Hrs



Repair Status

- Completed: Stage 1 & 2 Completed
- Completed: Ready for Inspection
- Repair Needed
- No Repair Needed
- Other: See Comments
- Unknown

- Helispot
- Drop Point
- Incident Command Post
- Staging Area
- Value at Risk
- Other
- Gate

- Bridge
- Structure Wrap
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck

- Hazard Tree
- Dozer Push
- Culvert
- Clean Up Area
- Mobile Weather Unit
- Repeater
- Hazard

- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Other
- Repair Line

- Contained Line
- Footbridge
- Highway
- Road - Light Duty - Dirt
- Road - Light Duty - Gravel
- Road - Light Duty - Paved
- Road - Light Duty - Unknown

- Road - Unimproved
- Trail
- Trail - Nat Rec/Scenic/Historic
- Bureau of Land Management (BLM)
- State
- Bureau of Indian Affairs (BIA)
- Private land

USFS Wilderness

NAD 1983 UTM Zone 10N
 G.T. Type 3
 10/27/2021, 2203hrs