



**Suppression Repair**  
**Div J/N**  
 McCash CA-SRF-000651  
 Oct 2, 2021  
 93,514 acres as of 9/30/2021, 1915 Hrs



Completed - Inspected	Unknown	Dip Site	Other	Road Repair	Culvert	Completed Burnout	R - R - Completed Road as Line	Contained Line	Wildfire Daily Fire Perimeter
Completed - Ready for Inspection	Other Property	Drop Point	Gate	Resource Location	Mobile Weather Unit	Completed Dozer Line	Access or Improved Road	Road - Light Duty - Paved	Private land
In Progress	Pump	Camp	Bridge	Repair Point	Repeater	Completed Fuel Break	Repair Line	Road - Light Duty - Unknown	Bureau of Land Management (BLM)
Repair Needed	Water Tank	Staging Area	Structure Wrap	Hazard Tree	Hazard	Completed Hand Line	Retardant Drop	Road - Unimproved	Bureau of Indian Affairs (BIA)
No Repair Needed	Hellspot	Value at Risk	Stream Crossing	Dozer Push	Restricted Water Source	Completed Mixed Construction Line	Fire Edge	Trail	USFS Wilderness
								Trail - Nat Rec/Scenic/Historic	

N  
  
 Mobile Maps  
 NAD 1983 UTM Zone 10N  
 AK Team 1 10/1/2021, 2211hrs  
 0 0.5 1 2 Miles