



<ul style="list-style-type: none"> Label Point Dip Site Branch Break Drop Point Staging Area Other Stream Crossing 	<ul style="list-style-type: none"> Road Repair Resource Location Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push Culvert Internet Access Safety Zone 	<ul style="list-style-type: none"> Hazard Water Source Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Dozer Line Planned Hand Line 	<ul style="list-style-type: none"> Access or Improved Road Road Repair Contained Wildfire Daily Fire Perimeter Other - See Comments In Use - Fire Management Needs Assessment Repair Needed 	<ul style="list-style-type: none"> In Progress No Repair Needed In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Inspected No Repair Needed 	<ul style="list-style-type: none"> Tahoe NF - DPA El Dorado NF - DPA SPI Parcels Private Lands within FED DPA Forest Boundary Western States Trail National Forest System Roads Roads
---	---	---	---	--	---

Suppression Repair GROUPS 1 & 2

9/25/2022 CA-TNF-001371

Created by: Jolley - GSS - READ Group

Suppression Repair GROUP 1 & 2

9/25/2022