



<ul style="list-style-type: none"> Label Point Helispot Sling Site Division Break Branch Break Drop Point Hot Spot - Spot Fire 	<ul style="list-style-type: none"> Value at Risk Water Development or Draft Site Structure Wrap Stream Crossing Road Repair Retardant in Avoidance Area Repair Point Fence - Cut/Damaged Dozer Push 	<ul style="list-style-type: none"> Clean Up Area Internet Access Safety Zone Hazard Water Source Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line 	<ul style="list-style-type: none"> Access or Improved Road Other Repair Line Contained Uncontained Wildfire Daily Fire Perimeter In Use - Fire Management In Use - Fire Management In Use - Fire Management Needs Assessment 	<ul style="list-style-type: none"> Repair Needed No Repair Needed Other - See Comments In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Inspected No Repair Needed 	<ul style="list-style-type: none"> Other - See Comments Tahoe NF - DPA El Dorado NF - DPA SPI Parcels Private Lands within FED DPA Forest Boundary National Forest System Roads Roads
---	--	---	--	--	---

Suppression Repair GROUP 4 SOUTH

9/27/2022 CA-TNF-001371

Created by: Jolley - GSS - READ Group

Suppression Repair GROUP 4 SOUTH

9/27/2022