



Suppression Repair GROUP 5A WEST
9/27/2022

Label Point	Stream Crossing	Safety Zone	Repair Line	In Progress	No Repair Needed
Dip Site	Road Repair	Hazard	Road Repair	No Repair Needed	Tahoe NF - DPA
Helispot	Resource Location	Completed Dozer Line	Contained	In Use - Fire Management	El Dorado NF - DPA
Branch Break	Repair Point	Completed Hand Line	Wildfire Daily Fire Perimeter	Needs Assessment	Private Lands within FED DPA
Drop Point	Landing or Log Deck	Completed Mixed Construction Line	Other - See Comments	In Progress	Forest Boundary
Value at Risk	Fence - Cut/Damaged	Completed Road as Line	In Use - Fire Management	Completed - Ready for Inspection	Western States Trail
Other	Dozer Push	Planned Dozer Line	Needs Assessment	Completed - Inspected	National Forest System Roads
	Culvert	Access or Improved Road	Repair Needed		Roads
	Internet Access				

Suppression Repair GROUP 5A

9/27/2022 CA-TNF-001371

Created by: Jolley - GIS - READ Group

Suppression Repair GROUP 5A WEST
9/27/2022