



SUPPRESSION REPAIR MOSQUITO
 9/29/2022

<ul style="list-style-type: none"> — In Use - Fire Management — Needs Assessment — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — Other - See Comments 	<ul style="list-style-type: none"> Wildfire Daily Fire Perimeter Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line 	<ul style="list-style-type: none"> Access or Improved Road Repair Line Road Repair D Dip Site M Mobile Retardant Base H Helispot S Sling Site X Division Break Branch Break 	<ul style="list-style-type: none"> A Drop Point C Camp S Staging Area H Hot Spot - Spot Fire V Value at Risk G Gate W Water Development or Draft Site 	<ul style="list-style-type: none"> S Structure Wrap C Stream Crossing R Road Repair A Retardant in Avoidance Area L Resource Location P Repair Point L Landing or Log Deck H Hazard Tree 	<ul style="list-style-type: none"> F Fence - Cut/ Damaged D Dozer Push C Culvert C Clean Up Area S Safety Zone W Hazard W Water Source R Restricted Water Source 	<ul style="list-style-type: none"> DPA City, County, District, Other State BLM ANCSA, Private USFS BIA, Tribal BOR 	<ul style="list-style-type: none"> Blodgett Forest SPI Camino District SPI Tahoe District
---	---	---	---	--	--	---	---

SUPPRESSION REPAIR MOSQUITO
 CA-TNF-001371
 9/29/2022

NAD83 UTM 10N
1:60,000



SUPPRESSION REPAIR MOSQUITO
 9/29/2022