



SUPPRESSION REPAIR MOSQUITO 10/3/2022	<ul style="list-style-type: none"> — In Use - Fire Management — Needs Assessment — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — Other - See Comments 	<ul style="list-style-type: none"> Wildfire Daily Fire Perimeter Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line 	<ul style="list-style-type: none"> Access or Improved Road Repair Line Road Repair Dip Site Helispot Sling Site Division Break Branch Break Drop Point 	<ul style="list-style-type: none"> A Camp S Staging Area L Lookout ● Hot Spot - Spot Fire ● Value at Risk G Gate W Water Development or Draft Site S Structure Wrap 	<ul style="list-style-type: none"> Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Fence - Cut/ Damaged 	<ul style="list-style-type: none"> Dozer Push Culvert Clean Up Area Safety Zone Hazard Water Source Restricted Water Source 	<ul style="list-style-type: none"> DPA City, County, Other State BLM ANCSA/Private USFS BIA, Tribal BOR 	<ul style="list-style-type: none"> Blodgett Forest SPI Camino District SPI Tahoe District SPI Existing Fuel Breaks 	<div style="text-align: center;"> <h2 style="margin: 0;">SUPPRESSION REPAIR MOSQUITO</h2> <p style="margin: 0;">CA-TNF-001371</p> <p style="margin: 0;">10/3/2022</p> </div>	<div style="text-align: center;"> </div> <div style="text-align: center;"> <p>NAD83 UTM 10N 1:60,000</p> </div> <div style="text-align: center;"> </div>	SUPPRESSION REPAIR MOSQUITO 10/3/2022
	<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="font-size: 2em; font-weight: bold;">↑</div> </div>										