




SUPPRESSION REPAIR MOSQUITO 10/6/2022	<ul style="list-style-type: none"> — In Use - Fire Management — Needs Assessment — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — Other - See Comments 	<ul style="list-style-type: none"> Wildfire Daily Fire Perimeter Contained Fire Edge Uncontained Fire Edge Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line 	<ul style="list-style-type: none"> Completed Road as Line Access or Improved Road Repair Line Road Repair Dip Site Hellsport Sling Site Division Break Branch Break 	<ul style="list-style-type: none"> Drop Point Camp Staging Area Lookout Hot Spot - Spot Fire Value at Risk Gate Water Development or Draft Site 	<ul style="list-style-type: none"> Structure Wrap Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree 	<ul style="list-style-type: none"> Fence - Cut/ Damaged Dozer Push Culvert Clean Up Area Safety Zone Hazard Water Source Restricted Water Source 	<ul style="list-style-type: none"> DPA City, County, Other State BLM ANCSA/Private USFS BIA, Tribal BOR 	<ul style="list-style-type: none"> Blodgett Forest SPI Camino District SPI Tahoe District SPI Existing Fuel Breaks 	<p>SUPPRESSION REPAIR MOSQUITO</p> <p>CA-TNF-001371</p> <p>10/6/2022</p>	  <p>0 1 2 3 Miles</p> <p>NAD83 UTM 10N 1:60,000</p> 	SUPPRESSION REPAIR MOSQUITO 10/6/2022
---	---	--	---	--	--	--	--	--	---	--	---