



SUPPRESSION REPAIR
MOSQUITO
 10/10/2022

<ul style="list-style-type: none"> Wildfire Daily Fire Perimeter Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Access or Improved Road Repair Line Road Repair Contained Fire Edge 	<ul style="list-style-type: none"> Uncontained Fire Edge Dip Site Helispot Sling Site Division Break Branch Break Drop Point Camp Staging Area Hot Spot - Spot Fire 	<ul style="list-style-type: none"> Value at Risk Gate Water Development or Draft Site Culvert Stream Crossing Road Repair Returnfall in Avoidance Area Resource Location Repair Point Landing or Log Deck 	<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments 	<ul style="list-style-type: none"> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected Other - See Comments DPA State BLM 	<ul style="list-style-type: none"> USFS BOR SPI Tahoe District Primary Highway Paved Roads Dirt (Not Paved) Stage 2 Stage 2
---	---	---	---	--	---

SUPPRESSION REPAIR
MOSQUITO
 CA-TNF-001371
 10/10/2022

FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE

CALIFORNIA FIRE
INCIDENT MANAGEMENT
TEAM 12
"Adapt, Innovate, and Overcome"

0 3 Miles
 NAD83 UTM 11N 1:27,500

SUPPRESSION REPAIR
MOSQUITO
 10/10/2022