



SUPPRESSION REPAIR MOSQUITO
 10/10/2022

- | | | | | | | |
|--|--|--|---|--|---|---|
| <ul style="list-style-type: none"> — In Use - Fire Management Needs Assessment — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — Other - See Comments | <ul style="list-style-type: none"> — Wildfire Daily Fire Perimeter — Contained Fire Edge — Uncontained Fire Edge — Completed Dozer Line — Completed Hand Line — Completed Mixed Construction Line — Completed Road as Line — Access or Improved Road — Repair Line | <ul style="list-style-type: none"> — Road Repair — Dip Site — Sling Site — Division Break — Drop Point — Camp — Staging Area — Lookout — Hot Spot - Spot Fire — Value at Risk — Gate | <ul style="list-style-type: none"> — Water Development or Draft Site — Structure Wrap — Stream Crossing — Road Repair Retardant in Avoidance Area — Resource Location — Repair Point — Landing or Log Deck — Hazard Tree — Fence - Cut/Damaged — Dozer Push | <ul style="list-style-type: none"> — Culvert — Clean Up Area — Safety Zone — Hazard — Water Source — Restricted Water Source | <ul style="list-style-type: none"> — DPA — City, County, Other — State — BLM — ANCSA/Private — USFS — BIA, Tribal — BOR | <ul style="list-style-type: none"> — Blodgett Forest — SPI Camino District — SPI Tahoe District — SPI Existing Fuel Breaks — Stage 1 — Stage 2 — FSR 213 — Stage 1 — Stage 2 |
|--|--|--|---|--|---|---|


SUPPRESSION REPAIR MOSQUITO
 CA-TNF-001371
 10/10/2022




FOREST SERVICE
DEPARTMENT OF AGRICULTURE




CALIFORNIA FIRE INCIDENT MANAGEMENT TEAM 12
"Might, Impassion, and Overcome"





0 1 2 3 Miles

NAD83 UTM 10N 1:60,000



SUPPRESSION REPAIR MOSQUITO
 10/10/2022