


SUPPRESSION REPAIR MOSQUITO SOUTH
 10/11/2022

- | | | | | |
|---|--|--|--|---|
| <ul style="list-style-type: none"> — Wildfire Daily Fire Perimeter — Completed Dozer Line — Completed Fuel Break — Completed Hand Line — Completed Mixed Construction Line — Completed Road as Line — Access or Improved Road — Repair Line — Road Repair — Contained Fire Edge | <ul style="list-style-type: none"> — Uncontained Fire Edge — In Use - Fire Management — Needs Assessment — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — Other - See Comments — Dip Site — Helispot | <ul style="list-style-type: none"> — Sling Site — Division Break — Branch Break — Drop Point — Camp — Staging Area — Lookout — Hot Spot - Spot Fire — Value at Risk — Gate | <ul style="list-style-type: none"> — Water Development or Draft Site — Structure Wrap — Stream Crossing — Road Repair — Retardant in Avoidance Area — Resource Location — Repair Point — Landing or Log Deck — Hazard Tree — Fence - Cut/Damaged | <ul style="list-style-type: none"> — Dozer Push — Culvert — Clean Up Area — Safety Zone — Hazard — Water Source — Restricted Water Source — Stage 2 Needed — FSR 213 — Stage 2 Needed |
|---|--|--|--|---|

SUPPRESSION REPAIR
MOSQUITO - SOUTH
 CA-TNF-001371
 10/11/2022



SUPPRESSION REPAIR MOSQUITO SOUTH
 10/11/2022

