



**FSR - SOUTH**  
**MOSQUITO**  
10/17/2022

- |  |   |   |   |   |
|--|---|---|---|---|
| <ul style="list-style-type: none"> <li>Wildfire Daily Fire Perimeter</li> <li>Completed Dozer Line</li> <li>Completed Fuel Break</li> <li>Completed Hand Break</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Access or Improved Road</li> <li>Road Repair</li> <li>Contained Fire Edge</li> <li>Uncontained Fire Edge</li> </ul> | <ul style="list-style-type: none"> <li>In Use - Fire Management</li> <li>Needs Assessment</li> <li>Repair Needed</li> <li>In Progress</li> <li>Completed - Ready for Inspection</li> <li>Completed - Inspected</li> <li>Other - See Comments</li> <li>Dip Site</li> <li>Helispot</li> <li>Sling Site</li> <li>Drop Point</li> <li>Staging Area</li> </ul> | <ul style="list-style-type: none"> <li>Lookout</li> <li>Hot Spot - Spot Fire</li> <li>Value at Risk</li> <li>Gate</li> <li>Water Development or Draft Site</li> <li>Structure Wrap</li> <li>Stream Crossing</li> <li>Road Repair</li> <li>Retardant in Avoidance Area</li> <li>Resource Location</li> <li>Repair Point</li> <li>Camp</li> <li>Landing or Log Deck</li> <li>Hazard Tree</li> </ul> | <ul style="list-style-type: none"> <li>Fence - Cut/Damaged</li> <li>Dozer Push</li> <li>Culvert</li> <li>Clean Up Area</li> <li>Safety Zone</li> <li>Hazard</li> <li>Water Source</li> <li>Restricted Water Source</li> </ul> | <ul style="list-style-type: none"> <li>DPA</li> <li>SPI Existing Fuel Breaks</li> <li>Blodgett Forest</li> <li>Stage 2 Needed</li> <li>FSR 213</li> <li>Stage 2 Needed</li> <li>Division Break</li> <li>Branch Break</li> </ul> |
|--|---|---|---|---|

**FSR - SOUTH**  
**MOSQUITO**  
CA-TNF-001371  
10/17/2022

0 1 2 3 Miles  
NAD83 UTM 11N 1:36,000

**FSR - SOUTH**  
**MOSQUITO**  
10/17/2022