


SUPPRESSION REPAIR MOSQUITO SOUTH 10/27/2022

- Drop Point
- ⊙ Gate
- ◆ Water Development or Draft Site
- ◆ Stream Crossing
- ◆ Road Repair
- ◆ Repair Point
- ◆ Dozer Push
- In Use - Fire Management
- Repair Needed
- In Progress
- Completed - Inspected
- No Repair Needed
- Needs Assessment
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- DPA
- SPI Tahoe District

**SUPPRESSION REPAIR
MOSQUITO**
CA-TNF-001371
10/27/2022



SUPPRESSION REPAIR MOSQUITO SOUTH 10/27/2022