



**HAZARD TREE MOSQUITO 10/28/2022**

**HAZARD TREE VOLCANOVILLE | REPAIR ROADS GROUP**

**MOSQUITO**  
CA-TNF-001371  
10/28/2022

<ul style="list-style-type: none"> <li>— Contained Fire Edge</li> <li>— In Progress</li> <li>— Hazard Tree Abatement</li> <li>— SPI Camino District</li> <li>— DPA</li> </ul>	<ul style="list-style-type: none"> <li>● Dip Site</li> <li>● Helispot</li> <li>● Division Break</li> <li>● Drop Point</li> <li>● Camp</li> <li>● Gate</li> <li>● Stream Crossing</li> <li>● Road Repair</li> <li>● Retardant in Avoidance Area</li> <li>● Repair Point</li> </ul>	<ul style="list-style-type: none"> <li>● Dozer Push</li> <li>● Culvert</li> <li>● Clean Up Area</li> <li>● Water Source</li> <li>● Completed Dozer Line</li> <li>● Completed Hand Line</li> <li>● Completed Road as Line</li> <li>● Access or Improved Road</li> <li>● Needs Assessment</li> <li>● Repair Needed</li> </ul>	<ul style="list-style-type: none"> <li>■ Completed - Inspected</li> <li>■ Needs Assessment</li> <li>■ Completed - Inspected</li> <li>■ SPI Existing Fuel Breaks</li> <li>■ SPI Fuel Breaks</li> <li>■ Blodgett Forest</li> <li>■ SPI Camino District</li> </ul>
---	---	---	---

**HAZARD TREE MOSQUITO 10/28/2022**