



**HAZARD TREE
MOSQUITO
10/31/2022**

HAZARD TREE VOLCANOVILLE | REPAIR ROADS GROUP

MOSQUITO
CA-TNF-001371
10/31/2022

<ul style="list-style-type: none"> — Contained Fire Edge — SPI Camino District □ DPA 	<ul style="list-style-type: none"> — In Progress — Hazard Tree Abatement 	<ul style="list-style-type: none"> ● Dip Site ● Helispot ⌋ Division Break ● Drop Point ■ Camp ⊙ Gate ⊙ Stream Crossing ● Road Repair ● Retardant in Avoidance Area ● Repair Point 	<ul style="list-style-type: none"> ● Dozer Push ● Culvert ● Clean Up Area ● Water Source ⊙ Completed Dozer Line — Completed Hand Line — Completed Road as Line — Access or Improved Road ● Needs Assessment ● Repair Needed 	<ul style="list-style-type: none"> ■ Completed - Inspected ■ Needs Assessment ■ Completed - Inspected ■ SPI Existing Fuel Breaks ■ SPI Fuel Breaks ■ Blodgett Forest ■ SPI Camino District
---	--	---	---	---

↑

**HAZARD TREE
MOSQUITO
10/31/2022**