



Suppression Repair Final Map

Mosquito Fire
 CA-TNF-001371
 October 30, 2022
 76,788 Acres



- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Dip Site
- Helispot
- △ Sling Site
-) Division Break
- | Branch Break
- Drop Point
- X Closure
- △ Camp
- S Staging Area
- ! Lookout
- Hot Spot - Spot Fire
- ! Value at Risk
- Landmark
- ⊠ Gate
- ⊥ Bridge
- ⊠ Water Development or Draft Site
- ⊠ Structure Wrap
- ⊠ Stream Crossing
- ⊠ Road Repair
- ⊠ Retardant in Avoidance Area
- ! Resource Location
- ⊠ Repair Point
- ⊠ Landing or Log Deck
- ⊠ Hazard Tree
- ⊠ Fence - Cut/Damaged
- ⊠ Dozer Push
- ⊠ Culvert
- ⊠ Clean Up Area
- △ Safety Zone
- △ Hazard
- W Water Source
- W Restricted Water Source
- XXXX Completed Dozer Line
- 〰 Completed Fuel Break
- H—H Completed Hand Line
- M—M Completed Mixed Construction Line
- R—R Completed Road as Line
- Repair Line
- - - Road Repair
- Access or Improved Road
- Contained

| | | |
|---|---|--|
| Dozer Line 1 Mile To Go | Dozer Line 4 Miles In Progress | Dozer Line 220 Miles Completed |
| Hand Line <1 Mile To Go | Hand Line Currently 0 Hand Lines In Progress | Hand Line 35 Miles Completed |
| Road Repair 2 Miles To Go | Road Repair 4 Miles In Progress | Road Repair 103 Miles Completed |



1:150,000